



Department of Commerce
BUILDING CODES DIVISION

401 LABOR & INDUSTRIES BUILDING, SALEM, OREGON 97310 PHONE 378-4133

December 10, 1984

RE: SPECIAL INSPECTION

A Special Inspection was conducted at Rajneeshpuram on December 7, 1984 by State Electrical Inspector Frank Evans.

Frank disconnected approximately 250 tents at the Rajneeshpuram Ranch on Friday, December 7, 1984. The violations consisted of the following:

- 1) Permits - ORS 479.550 "No work on new electrical installation until permit issued. Except as provided in ORS 479.540, no person shall work on any new electrical installation for which a permit has not been issued."
- 2) NEC Article 110-14(b) Splices. All splices done, using approved materials.
- 3) NEC Article 210-20. Overcurrent protection for conductors. (12-2 U.F. was fused at 100 amps)
- 4) NEC Article 250-5(A). AC circuits of less than 50 volts shall be grounded.
- 5) NEC Article 300-5(D). Protections of conductors on poles also entering tents.
- 6) NEC Article 300-5(E). Splices and taps. (By materials indentified for the purpose).
- 7) NEC Article 300-9. All metal enclosures and material shall be grounded as per 250.
- 8) NEC Article 725-15(b). Insulation of conductors.
- 9) NEC Article 725-35. Overcurrent protection for conductors.
- 10) NEC Article 725-38(A-1). Wiring methods on load side of over-current protection.
- 11) NEC Article 410-16(A). Fixture will be supported from outlet boxes.

Special Inspection Rajneeshpuram
December 10, 1984
Page 2

- 12) NEC Article 300-15. Junction boxes required.
- 13) NEC Article 300-5(Table). Underground cables (depth of).

Report by Bob Turpin as per phone conversation with Frank Evans on
December 10, 1984.

BT:jk